Red = SI Support Center

Green = Dredging Contractor
Orange = Inspection Contractor
Blue = Local Corps District

Certification Verification Procedure After Contract Award

District/Field Office notifies SI Center of Project via e-mail and requests SI certification status of proposed plant

FULLY CERTIFIED-

HOPPER -

SI Center e-mails copy of SI Letter of Certification to local POC (If certification due to expire during this project initiate SOP for Annual Certification)

SCOW -

(Scow profiles, lowest to highest: Tracking – Monitoring – Ullage – TDS)

Certification is good if scow is certified for equal or higher level SI profile –

SI Center e-mails copy of SI Letter of Certification to local POC (If certification due to expire during this project, initiate SOP for Annual Certification)

Is certified for lower level SI profile-

Install additional instrumentation, calibrate sensors and update DPIP, Follow procedures for annual certification on accelerated time frame (inspection completed prior to actual start of project)

CONDITIONALLY CERTIFIED-

HOPPER OR SCOW-

SI Center notifies local POC of outstanding deficiencies Local district decides whether to address deficiencies before start of dredging activities or allows time to correct as work

Contractor corrects deficiencies *Issue Letter of Certification*

NO CERTIFICATION, CERTIFICATION EXPIRED OR NOT IN COMPLIANCE-

HOPPER OR SCOW-

SI Center notifies local POC of non-compliance

Contractor initiates SOP for Annual Certification on accelerated time frame (inspection completed prior to actual start of project)